

Detailed Report ▾

2015 Kia Forte

Vehicle Identification Number: KNAFX4A67F5333708

→ Search Another VIN (/vehicle/land.php)



Accident/Junk/Salvage/Insurance Records
 Accident/Junk/Salvage/Insurance Records



Vehicle Recalls Available: 91



Vehicle Age: 2 year(s)



Assembly Location: South Korea Hwasung, South Korea



Body Style: Sedan



(https://d3rdv3saj7j6nd.cloudfront.net/image/kia/2015-kia-forte-ex-sedan/2015-kia-forte-ex-sedan-angular-front.jpg)

2015 Kia Forte
 VIN: KNAFX4A67F5333708
 LX
 1.8L I4 145hp 130ft. lbs.

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

DATE	MILEAGE	SOURCE	DETAILS
2014		Original Manufacturer	Fuel Economy Test 25 MPG Hwy / 37 MPG City
2014		Original Manufacturer	Shipped to Dealer - Original MSRP: 15890
2014		Original Manufacturer	Manufactured in South Korea Hwasung, South Korea
02-12-2015	23 mi.	Florida	<u>Historical Odometer Record</u>
10-02-2015	23 mi.	Florida	<u>Historical Odometer Record</u>
05-06-2016		Tallahassee, FL - Accident	
05-06-2016		Tallahassee, FL - Accident	
05-06-2016		State Accident Record	FL
06-06-2016		State Accident Record	FL
07-30-2016		State Accident Record	FL
04-08-2017	21,931 mi.	Indiana	<u>Current Odometer Record</u>
09-18-2017		Theft Database	Vehicle Status : No Stolen Records Available
09-18-2017		Edmunds - True Market Value	Trade-In : \$9,065 Private Sale : \$10,682 Dealers Retail : \$12,005
2020	60,000 mi.	Kia	Basic Warranty: 3 years
2020	100,000 mi.	Kia	Corrosion Warranty: 3 years

DATE	MILEAGE	SOURCE	DETAILS
2020	60,000 mi.	Kia	Roadside Assistance: 3 years
2025	100,000 mi.	Kia	Powertrain Warranty: 8 years

Odometer Records Source : NMVTIS

DATE	STATE OF TITLE	RECORD TYPE	MILEAGE	VIN
02-12-2015	Florida	Historical	23 mi.	KNAFX4A67F5333708
10-02-2015	Florida	Historical	23 mi.	KNAFX4A67F5333708
04-08-2017	Indiana	Current	21931 mi.	KNAFX4A67F5333708

Accident Records

This section identifies accident records on vehicle history are composed of a number of state sources and some independent agencies, they are based strictly on the information that is available to us.



No Accident Records!

Previous Vehicle Uses

This section identifies if a vehicle has previously been used as a rental, taxi, police, or test vehicle.

4 Vehicle Uses Checked

0 Event(s) Reported

No Rental Use Record

No Issues Found

No Taxi Use Record

No Issues Found

No Police Use Record

No Issues Found

No Test Use Record

No Issues Found

Theft Records

No Theft or Theft Recovery Records Found !

Lien / Impound / Export Records

No Lien / Impound / Export Records Found!

Junk / Salvage / Insurance Record Source : NMVTIS

No Junk / Salvage / Insurance Record Found!

Salvage Auction Record

No Salvage Auction Record !

Sales Records

No sales records found!

ASSUMPTIONSCurrent Mileage: 34,039 milesTime Period: Past 6 months**ESTIMATES**

Market Value: \$11,173 - \$13,787

Estimate Certainty: 99%

POWERED BYVinAudit.com

Vehicle Recalls

Recalls:0

Service Bulletins: 0

No vehicle recalls records found!

Technical Service Bulletins (TSBs)

These "secret warranties," TSBs cover known problems and provide repair instructions for service technicians and accordingly are distributed to all of the manufacturer's dealerships. Generally these repairs will be free of charge only if the vehicle is still under warranty.

DATE	COMPONENT	DETAILS
05-29-2013	100000 Power Train	Tsb 6-speed A T Transmission Adaptive Values Reset Relearn - This Bulletin Provides The Procedures Necessary To Reset And Relearn The Adaptive Values After Transmission Replacement Or Reprogramming Replacement Of The Ecm Pcm
05-19-2014	073200 Fuel System, Gasoline:fuel Injection System:injectors	Pit Stop Gdi Injector Spray Tip Deposits - A Design Feature Of Vehicles Equipped With A Gasoline Direct Injection Gdi System Is The Placement Of Each Fuel Injector Directly Into The Engine Cylinder Head Assembly Therefore It Is Compleat
05-19-2014	070000 Fuel System, Gasoline	Pit Stop Gdi Injector Spray Tip Deposits - A Design Feature Of Vehicles Equipped With A Gasoline Direct Injection Gdi System Is The Placement Of Each Fuel Injector Directly Into The Engine Cylinder Head Assembly Therefore It Is Compleat
05-22-2014	353000 Equipment:electrical	Tsb 6 Spd A T Solenoid Replacement Dtc P0741 - This Bulletin Provides Information Relating To The Replacement Of The Damper Clutch D C Solenoid On 6-speed Automatic Transaxles With Dtc P0741 Active Or History Instead Of Replacing Th
06-20-2014	353600 Equipment:air Conditioner	Tsb Testing A C Compressor Function Using Gds - This Bulletin Provides Information On A New Procedure To Test A C Compressor Function Using The Gds
09-04-2014	113000 Electrical System:starter Assembly	Pitstop Remote Start System Diagnostic Hotline - When Diagnosing Remote Start Systems Refer To The Table Shown In This Article For Detailed Information On Applicable Models Model Year And System Supplier Along With The Applicable Hotlin
10-01-2014	060000 Engine (pws)	Kia My Forte 2014-2015 Some Models May Experience A Hard Or No Start While Stationary *lj
10-07-2014	356000 Equipment Adaptive	Tsb General Information And Diagnosis For Smart Key Fob Systems And Start Stop Buttons - This Bulletin Provides Information Related To The Smart Key Systems On Vehicles Equipped With A T Automatic Transaxle And Start Stop Buttons Ssb
10-14-2014	113000 Electrical System:starter Assembly	Pitstop No Start Or Hard To Start Concerns - Some 2014 2015my Forte Koup 5 Dr Equipped With A 1 6l Gdi Turbo And Produced Before July 14 2014 May Experience A Hard To Start Concern Or Idle Rpm Fluctuations While Stationary If You Enco
10-14-2014	072100 Fuel System, Gasoline:delivery:fuel Pump	Pitstop No Start Or Hard To Start Concerns - Some 2014 2015my Forte Koup 5 Dr Equipped With A 1 6l Gdi Turbo And Produced Before July 14 2014 May Experience A Hard To Start Concern Or Idle Rpm Fluctuations While Stationary If You Enco

DATE	COMPONENT	DETAILS
10-14-2014	092100 Fuel System, Other:delivery;fuel Pump	Pitstop No Start Or Hard To Start Concerns - Some 2014 2015my Forte Koup 5 Dr Equipped With A 1 6l Gdi Turbo And Produced Before July 14 2014 May Experience A Hard To Start Concern Or Idle Rpm Fluctuations While Stationary If You Enco
02-13-2015	110000 Electrical System	Tsb Service Action Uvo Head Unit Replacement Sa184 - This Bulletin Provides The Procedure To Replace The Uvo Head Unit On Some Of 2015my Soul Ps Sportage Sl Sedona Yp And Forte Yd Vehicles Which May Exhibit A Condition In Whic
03-27-2015	110000 Electrical System	Null
03-27-2015	350000 Equipment	Null
04-10-2015	350000 Equipment	Tsb Tpms Sensor Replacement - This Bulletin Provides The Procedure To Replace The Tpms Sensors On Some 2014 2015my Forte Yd Vehicles Produced From February 18 2013 Through March 31 2015 Which May Exhibit A Tpms Light Illuminated In T
04-10-2015	199000 Tires:pressure Monitoring And Regulating Systems	Tsb Tpms Sensor Replacement - This Bulletin Provides The Procedure To Replace The Tpms Sensors On Some 2014 2015my Forte Yd Vehicles Produced From February 18 2013 Through March 31 2015 Which May Exhibit A Tpms Light Illuminated In T
04-24-2015	060000 Engine (pws)	Null
04-24-2015	180000 Vehicle Speed Control	Null
05-13-2015	350000 Equipment	Null
05-13-2015	118000 Electrical System: Software	Null
05-13-2015	110000 Electrical System	Null
05-26-2015	110000 Electrical System	Tsb Service Action Uvo System Upgrade Sa193 - This Bulletin Provides The Procedure For Upgrading The Uvo System On Some 2014my Forte Yd Vehicles Produced From June 1 2013 Through December 31 2013 As Part Of A Kia J D Power Pilot
05-26-2015	350000 Equipment	Tsb Service Action Uvo System Upgrade Sa193 - This Bulletin Provides The Procedure For Upgrading The Uvo System On Some 2014my Forte Yd Vehicles Produced From June 1 2013 Through December 31 2013 As Part Of A Kia J D Power Pilot
05-26-2015	118000 Electrical System: Software	Tsb Service Action Uvo System Upgrade Sa193 - This Bulletin Provides The Procedure For Upgrading The Uvo System On Some 2014my Forte Yd Vehicles Produced From June 1 2013 Through December 31 2013 As Part Of A Kia J D Power Pilot
06-01-2015	103100 Power Train:automatic Transmission:control Module (tcm, Pcm)	Null
06-01-2015	100000 Power Train	Null
06-01-2015	100000 Power Train	Null
06-26-2015	118000 Electrical System: Software	Tsb Navigation Head Unit Sd Card Replacement - This Bulletin Describes The Sd Card Exchange Replacement Procedure Related To Error Messages That May Be Displayed On The Navigation Screen When The Incorrect Sd Card Is Inserted Note Only N
06-26-2015	353500 Equipment:electrical:navigational System(global Positioning System)	Tsb Navigation Head Unit Sd Card Replacement - This Bulletin Describes The Sd Card Exchange Replacement Procedure Related To Error Messages That May Be Displayed On The Navigation Screen When The Incorrect Sd Card Is Inserted Note Only N
06-26-2015	110000 Electrical System	Tsb Navigation Head Unit Sd Card Replacement - This Bulletin Describes The Sd Card Exchange Replacement Procedure Related To Error Messages That May Be Displayed On The Navigation Screen When The Incorrect Sd Card Is Inserted Note Only N
06-26-2015	353500 Equipment:electrical:navigational System(global Positioning System)	Tsb Navigation Head Unit Sd Card Replacement - This Bulletin Describes The Sd Card Exchange Replacement Procedure Related To Error Messages That May Be Displayed On The Navigation Screen When The Incorrect Sd Card Is Inserted Note Only N

DATE	COMPONENT	DETAILS
07-01-2015	060000 Engine (pws)	Kia Crankshaft Position Sensor Ckp Variation Has Not Learned Causing Misfire Of Engine And Malfunction Indicator Light Mil To Come In Dash Model All No Years Listed *pe
07-01-2015	118000 Electrical System: Software	Null
07-01-2015	060000 Engine (pws)	Null
07-14-2015	110000 Electrical System	Null
08-03-2015	100000 Power Train	Tsb 6-spd A T Adaptive Value Reset Relearn - This Bulletin Provides The Procedures Necessary To Reset And Relearn The Adaptive Values After Transmission Replacement Or Reprogramming Replacement Of The Pcm Tcm After The Adaptive Values A
08-12-2015	118000 Electrical System: Software	Tsb Identifying Head Unit Software Version For Direct Exchange - This Bulletin Provides The Procedure On How To Identify And Record The Head Unit Software Level On Various Head Unit Platforms And Generations This Procedure Will Now Be Req
08-12-2015	110000 Electrical System	Tsb Identifying Head Unit Software Version For Direct Exchange - This Bulletin Provides The Procedure On How To Identify And Record The Head Unit Software Level On Various Head Unit Platforms And Generations This Procedure Will Now Be Req
09-29-2015	060000 Engine (pws)	Tsb Proper Oil Grade Viscosity Selection For Turbo Equipped Vehicles - This Bulletin Provides Information Related To The Proper Engine Oil Grade Viscosity To Be Used When Servicing Vehicles Equipped With A Turbocharger In Addition To
10-06-2015	355200 Equipment:other:owners/service/other Manual	Pre-delivery Inspection Pdi And Owner Delivery Folder Program - All Models Excluding K900 And Soul Ev -kia Motors America Inc Is Pleased To Announce The Launch Of An All-new Pre-delivery Inspection Pdi And Owner Delivery Folder Progra
10-06-2015	350000 Equipment	Pre-delivery Inspection Pdi And Owner Delivery Folder Program - All Models Excluding K900 And Soul Ev -kia Motors America Inc Is Pleased To Announce The Launch Of An All-new Pre-delivery Inspection Pdi And Owner Delivery Folder Progra
10-09-2015	350000 Equipment	Simplified Uvo E-services Activation Procedure - This Article Outlines The Simplified Activation Procedure For Vehicles Equipped With Uvo E-services Excluding 2016 K900 And Soul Ev
10-09-2015	353000 Equipment:electrical	Simplified Uvo E-services Activation Procedure - This Article Outlines The Simplified Activation Procedure For Vehicles Equipped With Uvo E-services Excluding 2016 K900 And Soul Ev
10-19-2015	110000 Electrical System	Tsb Kds - Audio Update Module Aum - The Gds Audio Update Module Aum Was Introduced In Fourth Quarter Of 2013 This Special Service Tool Sst Was Developed To Improve The Efficiency And Effectiveness Of Updating 2010my And Later Kia
10-19-2015	118000 Electrical System: Software	Tsb Kds - Audio Update Module Aum - The Gds Audio Update Module Aum Was Introduced In Fourth Quarter Of 2013 This Special Service Tool Sst Was Developed To Improve The Efficiency And Effectiveness Of Updating 2010my And Later Kia
01-29-2016	284000 Back Over Prevention: Camera System	Tsb Rear View Camera Diagnosis Replacement - This Bulletin Provides Information To Diagnose And Or Replace The Rear View Camera Of Some Kia Vehicles See Table On Pg 6 For Specific Models And Production Dates Which May Exhibit Inadequat
02-12-2016	118000 Electrical System: Software	Combined Tsb Service Action Mil On With Dtc C1212 - Logic Improvement Sa216 - This Bulletin Provides Information Related To The Ecm Software Upgrade Of Some 2014 2015my Forte Yd Produced From December 7 2013 To April 16 2015 And So
03-02-2016	123000 Exterior Lighting:tail Lights	On Some 2014-2015 My Forte Vehicles Customers May Complain About Water Droplets Forming Inside The Rear Tail Lamp Lenses Following A Rainstorm Or After Washing Their Vehicle These Water Droplets Are More Visible At Night And The Quantity

DATE	COMPONENT	DETAILS
03-02-2016	350000 Equipment	On Some 2014-2015 My Forte Vehicles Customers May Complain About Water Droplets Forming Inside The Rear Tail Lamp Lenses Following A Rainstorm Or After Washing Their Vehicle These Water Droplets Are More Visible At Night And The Quantity
03-02-2016	160000 Structure	Tsb Water Leak Condensation In Rear Combination Tail Lamp S - On Some 2014 2015my Forte Yd Vehicles Customers May Complain About Water Droplets Forming Inside The Rear Tail Lamp Lenses Following A Rainstorm Or After Washing Their Vehic
03-02-2016	350000 Equipment	Tsb Water Leak Condensation In Rear Combination Tail Lamp S - On Some 2014 2015my Forte Yd Vehicles Customers May Complain About Water Droplets Forming Inside The Rear Tail Lamp Lenses Following A Rainstorm Or After Washing Their Vehic
03-02-2016	123000 Exterior Lighting:tail Lights	Tsb Water Leak Condensation In Rear Combination Tail Lamp S - On Some 2014 2015my Forte Yd Vehicles Customers May Complain About Water Droplets Forming Inside The Rear Tail Lamp Lenses Following A Rainstorm Or After Washing Their Vehic
04-21-2016	355200 Equipment:other:owners/service/other Manual	Combination Tsb Service Action Uvo System Upgrade Sa222 - This Bulletin Provides The Procedure For Upgrading The Uvo System On Some 2014 2016my Soul Ps Sorento Xma Optima Tf Qf Forte Yd And Sportage Sl Vehicles To Address
04-21-2016	118000 Electrical System: Software	Combination Tsb Service Action Uvo System Upgrade Sa222 - This Bulletin Provides The Procedure For Upgrading The Uvo System On Some 2014 2016my Soul Ps Sorento Xma Optima Tf Qf Forte Yd And Sportage Sl Vehicles To Address
04-28-2016	162300 Structure:body:door	Pitstop Frameless Window Short Drop Feature Inoperative - Some Forte Koup Yd Vehicles Produced Before October 1 2014 May Experience Difficulty When Opening Closing The Doors In Freezing Temperatures Due To The Operation Of The Short
04-28-2016	355200 Equipment:other:owners/service/other Manual	Pitstop Frameless Window Short Drop Feature Inoperative - Some Forte Koup Yd Vehicles Produced Before October 1 2014 May Experience Difficulty When Opening Closing The Doors In Freezing Temperatures Due To The Operation Of The Short
06-08-2016	118000 Electrical System: Software	Combination Tsb Service Action Uvo System Upgrade Sa222 - This Bulletin Provides The Procedure For Upgrading The Uvo System On Some 2014 2016my Soul Ps Sorento Xma Uma Optima Tf Hev Forte Yd Sportage Sl 2015 2016my Sedo
06-08-2016	110000 Electrical System	Combination Tsb Service Action Uvo System Upgrade Sa222 - This Bulletin Provides The Procedure For Upgrading The Uvo System On Some 2014 2016my Soul Ps Sorento Xma Uma Optima Tf Hev Forte Yd Sportage Sl 2015 2016my Sedo
06-23-2016	110000 Electrical System	Tsb Uvo Software Upgrade - Media Button Inoperative - This Bulletin Provides The Procedure For Upgrading The Uvo System Of Some 2014 2015my Sportage Sl Forte Yd Optima Tf Qf Optima Hybrid Tf Hev And Sorento Xma Vehicles Which
06-23-2016	118000 Electrical System: Software	Tsb Uvo Software Upgrade - Media Button Inoperative - This Bulletin Provides The Procedure For Upgrading The Uvo System Of Some 2014 2015my Sportage Sl Forte Yd Optima Tf Qf Optima Hybrid Tf Hev And Sorento Xma Vehicles Which
06-29-2016	060000 Engine (pws)	Tsb Combined Tsb Service Action Mil On With Dtc C1212 Logic Improvement Sa216 - This Bulletin Provides Information Related To The Ecm Software Upgrade Of Some 2014 2015my Forte Yd Produced From December 7 2013 To April 16 2015 An
06-29-2016	110000 Electrical System	Tsb Combined Tsb Service Action Mil On With Dtc C1212 Logic Improvement Sa216 - This Bulletin Provides Information Related To The Ecm Software Upgrade Of Some 2014 2015my Forte Yd Produced From December 7 2013 To April 16 2015 An
09-02-2016	020000 Suspension	Pitstop Clicking Noise From Front Suspension - Some 2014-2016my Forte Yd Vehicles May Exhibit A Clicking Type Noise From The Front Suspension When Carrying A Full Load Of Passengers And Turning The Wheel In Either Direction At Low Speeds

DATE	COMPONENT	DETAILS
09-21-2016	060000 Engine (pws)	Tsb Engine Vibration At Idle - This Bulletin Provides The Procedure To Replace The Alternator Pulley Some 2014-16my Forte Yd Vehicles With 1 8l And 2 0l Nu Engines May Experience An Unusual Engine Vibration At Idle That Is Sometimes Mor
09-30-2016	353600 Equipment:air Conditioner	Pitstop Hvac Receiver Dryer - Desiccant Replacement - In The Event Of A Hvac System Concern In Which Metal Particles Or Shards Have Contaminated The System The Desiccant Or The Entire A C Receiver Dryer Assembly May Need To Be Replaced T
10-31-2016	110000 Electrical System	Tsb Inhibitor Switch Diagnosis Information - This Bulletin Gives Information Regarding The Steps To Take Regarding The Diagnosis Of The Inhibitor Switch
10-31-2016	355200 Equipment:other:owners/service/other Manual	Tsb Inhibitor Switch Diagnosis Information - This Bulletin Gives Information Regarding The Steps To Take Regarding The Diagnosis Of The Inhibitor Switch
11-04-2016	170000 Latches/locks/linkages	Tsb Mandatory Replacement Of Locking Security Hardware - By Design Certain Fasteners Utilized In Various Kia Models Are Strictly Intended For One Time Use Though Not Limited To The Following Some Examples Are Axle Shaft Nuts With Sta
11-04-2016	356000 Equipment Adaptive	Tsb Mandatory Replacement Of Locking Security Hardware - By Design Certain Fasteners Utilized In Various Kia Models Are Strictly Intended For One Time Use Though Not Limited To The Following Some Examples Are Axle Shaft Nuts With Sta
11-30-2016	133000 Visibility:power Window Devices And Controls	Tsb Combined Tsb Service Action Rear Door Window Motor Replacement Sa260 - This Bulletin Describes The Procedure To Replace Both Rear Door Power Window Motors On Some 2014-15my Forte Yd Vehicles Produced From February 1 2013 Throu
11-30-2016	137200 Visibility:rear Window Wiper/washer:motor	Tsb Combined Tsb Service Action Rear Door Window Motor Replacement Sa260 - This Bulletin Describes The Procedure To Replace Both Rear Door Power Window Motors On Some 2014-15my Forte Yd Vehicles Produced From February 1 2013 Throu
01-18-2017	063100 Engine And Engine Cooling:exhaust System:emission Control	Pitstop Manual Evaporative Emissions Test For Hard To Find Small Leaks - If The Malfunction Indicator Lamp Mil Is Illuminated With Dtc S P0442 P0455 P0456 Or P0457 Evaporative Emissions System-leak Detected And The Evaporative Eva
01-18-2017	356000 Equipment Adaptive	Tsb Mandatory Replacement Of Locking Security Hardware - By Design Certain Fasteners Which Are Designed To Lock Into Place Once Fully Attached Are Utilized In Various Kia Models And Are Strictly Intended For One Time Use Some Example
01-18-2017	354000 Equipment:mechanical	Tsb Mandatory Replacement Of Locking Security Hardware - By Design Certain Fasteners Which Are Designed To Lock Into Place Once Fully Attached Are Utilized In Various Kia Models And Are Strictly Intended For One Time Use Some Example
03-21-2017	353600 Equipment:air Conditioner	Tsb Defogging Logic Normal Operation Disabling And Enabling - Starting With 2010my All Kia Vehicles Except Rio Jb Incorporate A Defogging Logic To Prevent The Interior Windows From Becoming Excessively Fogged Depending On The Spe
03-21-2017	130000 Visibility	Tsb Defogging Logic Normal Operation Disabling And Enabling - Starting With 2010my All Kia Vehicles Except Rio Jb Incorporate A Defogging Logic To Prevent The Interior Windows From Becoming Excessively Fogged Depending On The Spe
03-24-2017	118000 Electrical System: Software	Tsb Service Action Audio Software Upgrade Sa276 - This Bulletin Provides The Procedure To Upgrade The Audio Software On Some 2015my Soul Ps Sportage Sl Optima Tf Qf Forte Yd And Sorento Xma Vehicles To Incorporate Bluetoo
03-24-2017	118000 Electrical System: Software	Tsb Service Action Uvo Software Upgrade Sa277 - This Bulletin Provides The Procedure To Upgrade The Uvo Software On Some 2015my Soul Ps Sportage Sl Optima Tf Qf Forte Yd And Sorento Xma Vehicles To Incorporate Bluetooth

DATE	COMPONENT	DETAILS
04-17-2017	353400 Equipment:electrical:radio/tape Deck/cd Etc.	Tsb Uvo System Upgrade - This Bulletin Provides The Procedure For Upgrading The Uvo System On Some 2014-2016my Soul Ps Sorento Xma Uma Optima Tf Hev Forte Yd Sportage Si 2015-2016my Sedona Yp And 2014-2015 My Optima Q

62 Point Title Inspection Source : NMVTIS

This section identifies our 62 point title inspection searches for permanent negative flags associated with the vehicles VIN from the state DMV and other government agencies. The below title checks are all potential problems related to the title of this vehicle.

TITLE AND PROBLEM CHECK	0 EVENT(S) REPORTED
Flood damage Not Reported As A Flood damage To VehicleHistory	No Issues Found
Fire damage Not Reported As A Fire damage To VehicleHistory	No Issues Found
Hail damage Not Reported As A Hail damage To VehicleHistory	No Issues Found
Salt water damage Not Reported As A Salt water damage To VehicleHistory	No Issues Found
Vandalism Not Reported As A Vandalism To VehicleHistory	No Issues Found
Kit Not Reported As A Kit To VehicleHistory	No Issues Found
Dismantled Not Reported As A Dismantled To VehicleHistory	No Issues Found
Junk Not Reported As A Junk To VehicleHistory	No Issues Found
Rebuilt Not Reported As A Rebuilt To VehicleHistory	No Issues Found
Reconstructed Not Reported As A Reconstructed To VehicleHistory	No Issues Found
Salvage: Damage or Not Specified Not Reported As A Salvage: Damage or Not Specified To VehicleHistory	No Issues Found
Test Vehicle Not Reported As A Test Vehicle To VehicleHistory	No Issues Found
Refurbished Not Reported As A Refurbished To VehicleHistory	No Issues Found
Collision Not Reported As A Collision To VehicleHistory	No Issues Found
Salvage Retention Not Reported As A Salvage Retention To VehicleHistory	No Issues Found
Prior Taxi Not Reported As A Prior Taxi To VehicleHistory	No Issues Found
Prior Police Not Reported As A Prior Police To VehicleHistory	No Issues Found
Original Taxi Not Reported As A Original Taxi To VehicleHistory	No Issues Found
Original Police Not Reported As A Original Police To VehicleHistory	No Issues Found
Remanufactured Not Reported As A Remanufactured To VehicleHistory	No Issues Found

TITLE AND PROBLEM CHECK	0 EVENT(S) REPORTED
Gray Market Not Reported As A Gray Market To VehicleHistory	No Issues Found
Warranty Return Not Reported As A Warranty Return To VehicleHistory	No Issues Found
Antique Not Reported As A Antique To VehicleHistory	No Issues Found
Classic Not Reported As A Classic To VehicleHistory	No Issues Found
Agricultural Vehicle Not Reported As A Agricultural Vehicle To VehicleHistory	No Issues Found
Logging Vehicle Not Reported As A Logging Vehicle To VehicleHistory	No Issues Found
Street Rod Not Reported As A Street Rod To VehicleHistory	No Issues Found
Vehicle Contains Reissued VIN Not Reported As A Vehicle Contains Reissued VIN To VehicleHistory	No Issues Found
Replica Not Reported As A Replica To VehicleHistory	No Issues Found
Totaled Not Reported As A Totaled To VehicleHistory	No Issues Found
Owner Retained Not Reported As A Owner Retained To VehicleHistory	No Issues Found
Bond Posted Not Reported As A Bond Posted To VehicleHistory	No Issues Found
Memorandum Copy Not Reported As A Memorandum Copy To VehicleHistory	No Issues Found
Parts Only Not Reported As A Parts Only To VehicleHistory	No Issues Found
Recovered Theft Not Reported As A Recovered Theft To VehicleHistory	No Issues Found
Undisclosed Lien Not Reported As A Undisclosed Lien To VehicleHistory	No Issues Found
Prior Owner Retained Not Reported As A Prior Owner Retained To VehicleHistory	No Issues Found
Vehicle Non-conformity Uncorrected Not Reported As A Vehicle Non-conformity Uncorrected To VehicleHistory	No Issues Found
Vehicle Non-conformity Corrected Not Reported As A Vehicle Non-conformity Corrected To VehicleHistory	No Issues Found
Vehicle Safety Defect Uncorrected Not Reported As A Vehicle Safety Defect Uncorrected To VehicleHistory	No Issues Found
Vehicle Safety Defect Corrected Not Reported As A Vehicle Safety Defect Corrected To VehicleHistory	No Issues Found
VIN Replaced Not Reported As A VIN Replaced To VehicleHistory	No Issues Found
Gray Market: Non-compliant Not Reported As A Gray Market: Non-compliant To VehicleHistory	No Issues Found
Gray Market: Compliant Not Reported As A Gray Market: Compliant To VehicleHistory	No Issues Found
Manufacturer Buy Back Not Reported As A Manufacturer Buy Back To VehicleHistory	No Issues Found
Former Rental Not Reported As A Former Rental To VehicleHistory	No Issues Found

TITLE AND PROBLEM CHECK	0 EVENT(S) REPORTED
Salvage: Stolen Not Reported As A Salvage: Stolen To VehicleHistory	No Issues Found
Salvage: Reasons Other Than Damage or Stolen Not Reported As A Salvage: Reasons Other Than Damage or Stolen To VehicleHistory	No Issues Found
Disclosed Damage Not Reported As A Disclosed Damage To VehicleHistory	No Issues Found
Prior Non-Repairable / Repaired Not Reported As A Prior Non-Repairable / Repaired To VehicleHistory	No Issues Found
Crushed Not Reported As A Crushed To VehicleHistory	No Issues Found
Odometer: Actual Not Reported As A Odometer: Actual To VehicleHistory	No Issues Found
Odometer: Not Actual Not Reported As A Odometer: Not Actual To VehicleHistory	No Issues Found
Odometer: Tampering Verified Not Reported As A Odometer: Tampering Verified To VehicleHistory	No Issues Found
Odometer: Exempt from Odometer Disclosure Not Reported As A Odometer: Exempt from Odometer Disclosure To VehicleHistory	No Issues Found
Odometer: Exceeds Mechanical Limits Not Reported As A Odometer: Exceeds Mechanical Limits To VehicleHistory	No Issues Found
Odometer: May be Altered Not Reported As A Odometer: May be Altered To VehicleHistory	No Issues Found
Odometer: Replaced Not Reported As A Odometer: Replaced To VehicleHistory	No Issues Found
Odometer: Reading at Time of Renewal Not Reported As A Odometer: Reading at Time of Renewal To VehicleHistory	No Issues Found
Odometer: Discrepancy Not Reported As A Odometer: Discrepancy To VehicleHistory	No Issues Found
Odometer: Call Title Division Not Reported As A Odometer: Call Title Division To VehicleHistory	No Issues Found
Odometer: Exceeds Mechanical Limits Rectified Not Reported As A Odometer: Exceeds Mechanical Limits Rectified To VehicleHistory	No Issues Found

f Share on

Facebook (https://www.facebook.com/dialog/feed?app_id=184683071273&link=https://www.vehiclehistory.com/vehicle?K3AxbllZaDdTVWlvcFZoenF4WDFEOVZjbbk3RHphNUhPK0NLATZ3amVqUT0=&1505734652&picture=https://d3rdv3saj7j6nd.cloudfront.net/images/vehicle/sm/kia/2015-kia-forte-ex-sedan/2015-kia-forte-ex-sedan-grille.jpg&name=&caption=%20&description=&redirect_uri=http%3A%2F%2Fwww.facebook.com%2F)

Share on

Twitter (<https://twitter.com/home?status=Vehicle%20History%20For%20VIN%20KNAFX4A67F5333708%202015%20Kia%20Forte%20https://www.vehiclehistory.com/vehicle?K3AxbllZaDdTVWlvcFZoenF4WDFEOVZjbbk3RHphNUhPK0NLATZ3amVqUT0=&1505734652>)

Continue To Next Report Page > (/paging-vin-report-data/specifications.php?vin=KNAFX4A67F5333708)

VehicleHistory.com - Data Sources

- NMVTIS (Federal Government Salvage Database)
- Junk Yards
- Insurance Companies
- Salvage Yards
- Manufacturers
- Car Dealerships
- Auto Recyclers
- Auto Auctions
- Law Enforcement Agencies
- Collision Repair Facilities

*All states are required by law to report this information

To share this report with others, copy and paste this link:

<https://www.vehiclehistory.com/vehicle?K3AxbllZaDdTVWlvcFZoenF4v>

Copy to clipboard

Click Here To Print Page

Share on

Facebook (https://www.facebook.com/dialog/feed?app_id=184683071273&link=https://www.vehiclehistory.com/vehicle/K3AxbllZaDdTVWlvcFZoenF4WDFEovZjbkk3RHphNuhPK0NLatZ3amVqUT0=&1505734652&picture=https://d3rdv3saj7j6nd.cloudfront.net/images/vehicle/sm/2015-ki...
kia/2015-kia-forte-ex-sedan/2015-kia-forte-ex-sedan-grille.jpg&name=&caption=%20&description=&redirect_uri=http%3A%2F%2Fwww.facebook.com%2F

Share on

Twitter (https://twitter.com/home?status=Vehicle%20History%20For%20VIN%20KNAFX4A67F5333708%202015%20Kia%20Forte%20https://www.vehiclehistory.com/vehicle/K3AxbllZaDdTVWlvcFZoenF4WDFEovZjbkk3RHphNuhPK0NLatZ3amVqUT0=&1505734652)

Continue To Next Report Page > (/paging-vin-report-data/specifications.php?vin=KNAFX4A67F5333708)

NMVTIS Consumer Access Disclaimer

The National Motor Vehicle Title Information System (NMVTIS) is an electronic system that contains information on certain automobiles titled in the United States. NMVTIS is intended to serve as a reliable source of title and brand history for automobiles, but it does not contain detailed information regarding a vehicle's repair history.

All states, insurance companies, and junk and salvage yards are required by federal law to regularly report information to NMVTIS. However, NMVTIS does not contain information on all motor vehicles in the United States because some states are not yet providing their vehicle data to the system. Currently, the data provided to NMVTIS by states is provided in a variety of time frames; while some states report and update NMVTIS data in "real-time" (as title transactions occur), other states send updates less frequently, such as once every 24 hours or within a period of days. Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company (or other appropriate entity) to be a "total loss" or branded by a state titling agency. Conversely, an insurance carrier may be required to report a "total loss" even if the vehicle's titling-state has not determined the vehicle to be "salvage" or "junk."

Before making a decision to purchase a vehicle, consumers may wish to obtain an independent vehicle inspection, a NMVTIS Vehicle History Report, and consult other available vehicle information resources.

The information in NMVTIS includes:

Information from participating state motor vehicle titling agencies. Information on automobiles, buses, trucks, motorcycles, recreational vehicles, motor homes, and tractors. NMVTIS may not currently include commercial vehicles if those vehicles are not included in a state's primary database for title records (in some states, those vehicles are managed by a separate state agency), although these records may be added at a later time. Information on "brands" applied to vehicles provided by participating state motor vehicle titling agencies. Brand types and definitions vary by state, but may provide useful information about the condition or prior use of the vehicle.

Most recent odometer reading in the state's title record.

Information from insurance companies, and auto recyclers, including junk and salvage yards, that is required by law to be reported to the system, beginning March 31, 2009. This information will include if the vehicle was determined to be a "total loss" by an insurance carrier.

Information from junk and salvage yards receiving a "cash for clunker" vehicle traded-in under the Consumer Assistance to Recycle and Save Act of 2009 (CARS) Program.

Consumers are advised to visit www.vehiclehistory.gov for details on how to interpret the information in the system and understand the meaning of various labels applied to vehicles by the participating state motor vehicle titling agencies. NMVTIS data in this report has been obtained from VinAudit Inc., an Approved NMVTIS Data Provider

NEXT >
(/paging-vin-report-

Advertisement banner for Allied Sectional, Phenix Contact, and DataOne. Includes logos and text: "Build Your Cabinet with Confidence", "High-Performance Solutions for Complete Control", "PHENIX CONTACT", "LEARN MORE".

Data provided by DATAONE (https://www.dataonesoftware.com/)