

Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report

SAMENT INFO

Date of Inspection	07/14/2015
Purpose of Inspection	Actual Cash Value
Name of Inspector	Kevin Skurski
Vehicle Owner	Betty Lippold
Email Address	bettylippold@bellsouth.net
Tel #	678-476-0749
Inspection Location	Stone Mountain, GA



Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report

№ VEHICLE INFORMATION

Tag Number	PHQ6079
State	Georgia
VIN	2G1FP22S3S2197871
Year	1995
Make	Chervolet
Model	Camaro
Mileage	54,978
Mileage Category	Actual
Cylinders	6
Transmission	Automatic Shift
Drivetrain	2WD
Engine	Gasoline



Tel: 1-877-667-2326

C02 » Vehicle Inspection Report	I: 0056 Date: 07/14/2015
VEHICLE OPTIONS	
Alloy Wheels Additional Options	



Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report

□ P2





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report

□ P4





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report







Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report

□ P7





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report

□ P9





Car Appraisals & Claims LLC www.carappraisal.us Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report

□ P11





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report

□ P12





Tel: 1-877-667-2326

I: 0056

Date: 07/14/2015

C02 » Vehicle Inspection Report

♥ VEHICLE CONDITION

Seats	5
Carpet	5
Headliner	5
Doors / Interior Panels	5
Dash / Console	5
Glass	5
Body	5
Paint	4
Tires	4
Trim (including convertible tops if applicable)	5
Wheels	4
Engine	5
Transmission	5
Electrical or Accessories	5
Average Grade	4.79



Tel: 1-877-667-2326

	1: 0056
C02 » Vehicle Inspection Report	Date: 07/14/2015

ADDITIONAL DETAILS	
➤ Inspector's Grade	,
Very Good	\checkmark
Good	
Average	
Below Average	
Rough	