

Diminished Value of Georgia

1372 Peachtree St NE
Atlanta, GA 30309

(678) 404-0455

COLLISION REPAIR BILL

Customer: DOE, JOHN

Job Number:

Written By:
Adjuster:

Insured:	Insured, Company	Policy #:	000000-0	Claim #:	00-0000-00000
Type of Loss:	Liability	Date of Loss:	6/15/2024 10:30 PM	Days to Repair:	0
Point of Impact:	12 Front				

Owner:	Inspection Location:	Insurance Company:
DOE, JOHN	COLLISION CENTER NAME	INSURANCE COMPANIE
0000 CITY STATE	0000 LOCATION BLVD	INSURANCE - ALL
CITY, XX 00000-0000	CITY, XX 00000 Repair	Address
(000) 444-7225 Cell	Facility	
(000) 333-7225 Other	(678) 957-5260 Business	

Vehicle Drop Off Date:	02/14/2025	Promise Date: Vehicle	03/1/2025	Repair Start Date:	03/14/2025
Repair Completion Date:	03/1/2025	Pick Up/Return Date:	03/1/2025		

VEHICLE

2015 HOND Civic Sedan EX-L w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI GREY

VIN:	ABC10DEF991234567	Interior Color:	GRAY	Mileage In:	42,344	Vehicle Out:	03/1/2025
License:	XXX1234	Exterior Color:	GRAY	Mileage Out:			
State:	XX	Production Date:	4/2018	Condition:		Job #:	

TRANSMISSION	Air Conditioning	Stereo	Bucket Seats
Automatic Transmission	Intermittent Wipers	Search/Seek	Reclining/Lounge Seats
POWER	Tilt Wheel	CD Player	Leather Seats
Power Steering Power	Cruise Control	Auxiliary Audio Connection	Heated Seats
Brakes	Rear Defogger	SAFETY	WHEELS
Power Windows Power	Keyless Entry	Drivers Side Air Bag	Aluminum/Alloy Wheels
Locks	Alarm	Passenger Air Bag	PAINT
Power Mirrors	Message Center	Anti-Lock Brakes (4)	Clear Coat Paint
Heated Mirrors	Steering Wheel Touch Controls	4 Wheel Disc Brakes	OTHER
Power Driver Seat	Telescopic Wheel	Front Side Impact Air Bags	Fog Lamps
DECOR	Climate Control	Head/Curtain Air Bags	Traction Control
Dual Mirrors	Backup Camera	Hands Free Device	Stability Control
Tinted Glass	RADIO	ROOF	
Console/Storage	AM Radio	Electric Glass Sunroof	
CONVENIENCE	FM Radio	SEATS	

Estimate of Record

2015 HOND Civic Sedan EX-L w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI GREY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		QUARTER PANEL					
2	*	Rpr LT Quarter panel	04646TR0A91ZZ			<u>12.0</u>	2.2
		NOTE: INCLUDES TIME FOR ROUGH PULL					
3		Add for Clear Coat					0.9
4	#	Refn Basecoat Reduction					-0.5
5		REAR LAMPS					
6	**	Repl A/M LT Tail lamp assy	11-6574-00B	1	72.16	0.2	
7		REAR BUMPER					
8		O/H bumper assy				1.6	
9	** <>	Repl A/M Bumper cover	H7251	1	156.92	Incl.	3.0
		NOTE: LABOR: Time includes reflectors and lower cover.					
10		Overlap Major Non-Adj. Panel					-0.2
11		Add for Clear Coat					0.6
12		VEHICLE DIAGNOSTICS					
13	#	Repl Pre-Repair Scan (Pricing sourced through asTech)		1	15.00 X	0.3	
		NOTE: REQ. BY MANUF.					
14	#	Repl Post-Repair Scan (Pricing sourced through asTech)		1	15.00 X	0.6	
		NOTE: REQ. BY MANUF.					
15		MISCELLANEOUS OPERATIONS					
16	#	Rpr Rope Glass - Back Glass				0.3	
17	#	Rpr Cover Car					0.2
18	#	Repl Flex Additive		1	5.00 X		
19	#	Repl Restore Corrosion Protection		1	10.00 X	0.2	
20	#	Subl Recondition Wheel - Alloy (Includes Markup)		1	187.50 X		
21	#	Subl Suspension Alignment		1	89.95 X		
22	#	Electronic Signature for xxxxxx License # xxxxxx		1			
23		OTHER CHARGES					
24	#	Hazardous Waste Removal		1	5.00		
SUBTOTALS					556.53	15.2	6.2

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			229.08
Body Labor	15.2 hrs @	\$ 54.00 /hr	820.80
Paint Labor	6.2 hrs @	\$ 54.00 /hr	334.80
Paint Supplies	6.2 hrs @	\$ 40.00 /hr	248.00
Miscellaneous			322.45
Other Charges			5.00
Subtotal			1,960.13
Sales Tax	\$ 229.08 @	6.0000 %	13.74
County Tax	\$ 229.08 @	1.0000 %	2.29
Other Tax 1	\$ 229.08 @	1.0000 %	2.29
Total Cost of Repairs			1,978.45
Total Adjustments			0.00
Net Cost of Repairs			1,978.45